COPY OF EXTRACT FROM LLOYD'S LIST 2nd December 1953.

HILDINA .- Wick Radio; Dec.1 - Following received from Emitish motor trawler Velia:

At 8 22 a.m., G.M.T.: Mayday at 8 12 a.m. G.M.T., received from British motor trawler Gavina, MNXR, on 2042 kcs., that she was fast and turning over. No further details. Called two or three times but no reply, using last part of her call sign KR. My position NW. of Sule Skerry; Gavina's position last night WNW. of Michle Flugga.

At 8.33 a.m., G.M.T.: Ship in distress is not Gevine, it is possibly Hildina, MWY.

At 9 18 a.m., G.M.F.: We see now in 110 fathoms N. by W. W of Sule Skerry, we are picking up carley float with a number of men on board and caught glimpse of lifeboat and proceeding; will confirm ship's name later.

At 9.22 a.m., G.M.I.: Confirm mane of vessel motor trawler Hildina. Picked up survivors on carley float, proceeding to lifeboat.

At 9 29 a.m., G.M.T.: We have proked up lifeboat with one man, proceeding to search area for other survivors.

At 9 40 a.m., G.M.T.: We have picked up 10 survivors and now searching area. Crew say they saw ship go down and skipper and operator still on board; assuming 15 of crew, five still missing.

At 9 L9 a.m., G.M.T.: Approximate position 50 miles N. by W. $\frac{1}{2}$ W. of Sule. Sectry by bearing and depth of water.

At 10 16 a.m. G.M.T.: Nine survivors two dead, three went down with the ship, one still missing. Steam trawlers Monimia and Margaret Wicks still searching, we are proceeding to Stornoway for medical assistance. ————— Wick Radio Dec.1 ———— Trawler Hildina: Following received from British trawler Momimia.

At 11 41 a.m. C.M.T.: We are continuing the search with trawler Margaret -Wicks for about another hour. Have sighted wreckage but no further survivors seen yet.

At 12 47 p.m., G.M.T.: Found small boot and carley float in direction discated by aircraft search.

o. 1953.

. - Stornoway, Dec.2 - Fisetwood traviler Velia arrived at Stornoway his morning, landing nime survivors and one body from travier Hildina. Sue of Dec.2).

On the morning of 1st December while the s.t. "Hildina" with a crew of 15 was fishing in the North Sea, 50 miles from Orkney, ther trawl became caught on the sea bed. The sea at the time was moderate with a moderate to heavy swell and a westerly wind. While attempts were being made to free the trawl the vessel took n a heavy sea to starboard which caused it to list badly. There had previously been trouble with the motor generator operating the winch but it had been repaired: the heavy listing, however, once more put the winch out of action and the Mate, J. Moran, and Bosun, E. Sumner, were unable to put it into reverse or to unship the clutches and let the warps run as instructed by the Skipper. They thousasked the Skipper if they should chop the warps and, not hearing from him, they looked around for an axe with which to do so but could not find one. Water by this time was pouring through the starboard door leading to the accommodation and, although two of the deckhands, G.A. Hayes and J.A. Gardner, assisted by the Second Engineer J.H. Tranmer, attempted to shut it they were unable warping of the door.

The Chief Engineer F. Heidstra and Greaser Bond were on duty in the Engine Room looking after the main engines and the telegraph but water was pouring through the ventilator making their task almost impossible. They remained in the engine room until they received the signal to abandon ship and they had to leave by the port skylight as by then the engine room was flooded.

Two of the crew tried to launch the lifeboat but it overturned before launching. One of them, deckhand D. Atkinson, dived into the water and managed to hang on to the keel until rescued. Another, deckhand Benson, was drowned when he slipped through a lifebuoy. Others of the crew gathered on the port side and succeeded in launching the Carley Float which the sea overturned the crew managed to cling to it. Second Engineer Tranmer got astride the float and pulled Greaser Acton across his knee and held on to the Cook until they were picked up. The Radio Office Robertson remained at his post sending out distress signals. Three quarters-of-an-hour later ten out of fifteen of the crew were picked up by the s.t. "Velia" but unfortunately one, the Cook died later. The Chief Engineer was unconscious. Two of the crew, Dell, a deckhand, and Greaser Bond, had lost their hold of the float and been carried away. The Skipper and Radio Officer went down with the ship.

The "Velia" stayed in the vicinity to search for any other survivors until two other trawlers "Monimia" and "Margaret Wicks" arrived and took over the search. The "Velia" then proceeded to Stornoway and landed those already rescued.

use of it may be subject to convight restrictions. Further information is given in the 'Terms and that your conditions of supply of the National Archives' leaflets